


DIAGRAMS for the *Kodak X-Omat 5000 RA PROCESSOR* Service Code: 3425



Important

Qualified service personnel must repair this equipment.



H148_0004AA



HEALTH IMAGING

PLEASE NOTE The information contained herein is based on the experience and knowledge relating to the subject matter gained by Eastman Kodak Company prior to publication.

No patent license is granted by this information.

Eastman Kodak Company reserves the right to change this information without notice, and makes no warranty, express or implied, with respect to this information. Kodak shall not be liable for any loss or damage, including consequential or special damages, resulting from any use of this information, even if loss or damage is caused by Kodak's negligence or other fault.

 This equipment includes parts and assemblies sensitive to damage from electrostatic discharge. Use caution to prevent damage during all service procedures.

Table of Contents


Description	Page
Circuit Diagrams	3
AC Circuit	4
DC Circuit	6
Wiring Diagrams	8
Electrical	8
COMPONENT PLATE	10
External Components A	12
External Components B	14

Section 1: Circuit Diagrams


AC Circuit

NOTES:

1. SEE TRANSFORMER CONNECTION DIAGRAM FOR APPROPRIATE JUMPER CONFIGURATION




H148_0031EC_




H148_0032EC_


DC Circuit





H148_0033EC_




Electrical












External Components A




H148_0035EC_



H148_0036EC_





H148_0038EC_

Publication History

Publication Date	Publication No.	ECO No.	Changed Pages	File Name	Notes
01OCT95	5B6344	2649-029	All	di3425_1_029.doc	New Publication
10MAY02	5B6344	---	All	5b6344.fm	Revised to include information for the FLICKER UPGRADE KIT, 50 Hz equipment only.

Kodak and X-Omat are trademarks.